



MIXING AND USE INSTRUCTIONS

Zandur Gate Dressing No. 7

1. Mix thoroughly before use. Gate Dressing is properly mixed when it is of a uniform consistency.

2A. Spray Method

- a. Thin gate dressing down with water mixing 3 parts of water to 1 part of gate dressing.
- b. Brush off the gate and molds. Using a spray gun, spray the gate dressing on the gates from the top of the gate down to the top frame. Then spray the molds with Zandur cork mold coat.
- c. When you have finished, spray the gates a second time with gate dressing from top of the gate to the top frame.

2B. Brush Method

- a. Thin gate dressing down with 3 parts of water to 1 part of gate dressing.
- b. Brush molds off, spray mold with Zandur cork mold coat.
- c. Brush gate dressing on the gates from the top to the top frame.

3. If Gate Dressing is too thick, add additional water to achieve the desired results.

Keep from Freezing. Keep in a cool area out of sunlight and keep container closed.